

#### 708 Heartland Trail Suite 3000 Madison, WI 53717

608.826.3600 PHONE 608.826.3941 FAX

www.TRCsolutions.com

February 19, 2018

Mr. Michael Schmoller Hydrogeologist Wisconsin Department of Natural Resources 3911 Fish Hatchery Road Fitchburg, WI 53711

Subject: Madison-Kipp Corporation

BRRTS No. 02-13-578014

On-Site PCB Monitoring and Interim Remedy Status Report

Dear Mr. Schmoller:

On behalf of Madison-Kipp Corporation (MKC) and pursuant to the requirements of Paragraph 9(f)(i) of the Stipulation and Order for Judgment entered by the Court on November 27, 2017, TRC Environmental Corporation submits the attached report. We believe this concludes the requirements for submittals within 90 days of entry of the Stipulation and Order for Judgment.

Please let me or Mark Sheppard of MKC know if you have any questions regarding the attached report or if you are in need of further information.

Sincerely,

TRC Environmental Corporation

Katherine Vater, P.E.

Kuthen Vate

Project Manager

Attachment

cc: Peter Ramanauskas - USEPA

Tony Koblinski, Mark Sheppard - Madison-Kipp Corporation

David Crass - Michael Best & Friedrich LLP

063628-0040\22792281.1



# On-Site PCB Monitoring and Interim Remedy Status Report

Madison-Kipp Corporation 201 Waubesa Street Madison, Wisconsin

WDNR BRRTS #02-13-578014

February 2018

Prepared For Madison-Kipp Corporation 201 Waubesa Street Madison, Wisconsin 53704

Stephen Sellwood, P.G., Ph.D.

Senior Hydrogeologist

Katherine Vater, P.E.

Project Manager

# **Table of Contents**

1.	Introduction	
2.	Monitoring V	Vell Network2
	_	
3.	Groundwate	r Monitoring Plan
4.	Interim Rem	edy – Cap4
List o	f Tables	
Table	1	PCB Groundwater Monitoring Plan
List o	f Figures	
Figur	e 1	Well Locations Map
List o	f Appendices	
Appe	ndix A	Boring Logs, Monitoring Well Development Forms, Well Abandonment Forms, and Well Construction Forms
Appe	ndix B	Cap Maintenance Plan

# Section 1 Introduction

A Stipulation and Order for Judgment between the State of Wisconsin and Madison-Kipp Corporation (MKC) was entered on November 27, 2017. MKC operates an active manufacturing facility at 201 Waubesa Street (the facility, the Site). The Stipulation and Order for Judgment required that MKC complete the following actions within 90 days of entry:

- Monitoring Well Network modifications (see Section 2)
- Groundwater Monitoring Plan for on-going monitoring of polychlorinated biphenyls (PCBs) (see Section 3)
- Documentation of an Interim Remedy Cap, and on-going inspection through a Cap Maintenance Plan (see Section 4)

# Section 2 Monitoring Well Network

As required by Stipulation and Order for Judgment Paragraph 9(a)(i), four monitoring wells at the MKC facility (MW-22S, MW-22D, MW-23S, and MW-23D) were abandoned on January 16, 2018. These four wells were abandoned by filling the casings with 3/8-inch bentonite chips. Concrete was used to patch the facility floor at the four abandoned well locations. The well abandonment forms are included in Appendix A.

Also as required by Paragraph 9(a)(i), two new monitoring wells (MW-29D and MW-29S) were installed outside the building at the south end of the MKC facility on January 15 and 16, 2018. The location of the new well nest conforms to the requirements in the Stipulation and Order for Judgment and is shown on Figure 1. The boring for MW-29D was drilled using hollow-stem augers to a depth of approximately 29 feet and air rotary drilling to a depth of 50 feet. MW-29D was installed with five (5) feet of PVC screen from approximately 45 feet to 50 feet bgs. Weathered sandstone bedrock was encountered in the MW-29D borehole at a depth of approximately 29 feet and the well is screened within competent sandstone bedrock (Upper Lone Rock Formation). The boring for MW-29S was drilled using hollow-stem augers. MW-29S was installed with 10 feet of PVC screen from approximately 25 feet to 35 feet below ground surface (bgs), and is screened across weathered sandstone bedrock and the overlying unconsolidated fine-grained sand with silt. The monitoring wells were constructed in accordance with Wisconsin Administrative Code (WAC) Chapter NR 141. Boring logs and well construction forms are included in Appendix A.

Following installation, the wells were developed on January 18, 2018, by surging with a pump and pumping to remove sediment-laden water. MW-29D did not purge dry and was pumped between surging events until at least 10 well casing and filter pack volumes of water were removed. MW-29S was purged dry multiple times between surging and pumping. Monitoring well development forms are included in Appendix A.

# Section 3 Groundwater Monitoring Plan

Groundwater monitoring for PCBs will be conducted at the Site in compliance with the Stipulation and Order for Judgment, including Paragraphs 9(a)(ii-v).

MKC will conduct semi-annual sampling of the eight monitoring well sampling locations listed in Table 1 utilizing low-flow sampling techniques and laboratory analysis for PCBs using EPA SW-846 Method 8082. Semi-annual sampling is scheduled for April and October of each year.

Groundwater samples collected from the eight wells will be unfiltered. Analysis for Total Suspended Solids (TSS) and Total Dissolved Solids (TDS) data shall be included to evaluate the *in-situ* conditions present during the time of sample collection. These analyses will determine whether conditions at the time of sampling may be causing re-suspension and collection of PCB-impacted residual solids in the screened interval, potentially biasing the reported PCB concentration.

Analytical results of the semi-annual sampling will be provided within 60 days of each sampling event in a summary table.

After five years of semi-annual monitoring, e.g., following the October 2022 sampling event, the WDNR and MKC will review the sampling program and determine if the frequency and/or location of sampling can be reduced or discontinued.

# Section 4 Interim Remedy – Cap


The Stipulation and Order for Judgment outlines requirements for MKC to manage PCB-impacted soil beneath the manufacturing facility. Currently, the facility and associated paved surfaces serve as a protective cap, which is an interim remedy to prevent exposure to the soil. This report hereby documents that the concrete flooring/foundation/pavement are an interim remedy at the site and should be listed as such in the BRRTS database (see Paragraphs 9(f)(i), Stipulation and Order for Judgment).

A Cap Maintenance Plan is included in Appendix B and will be implemented by MKC.

Note that a separate Cap Maintenance Plan is currently in place for the majority of the paved parking lots at the site, as shown in GIS Registry Case Closure Request for BRRTS #02-13-576860 (included as an appendix to the Cap Maintenance Plan in Appendix B).

# Table 1 PCB Groundwater Monitoring Plan Madison-Kipp Corporation 201 Waubesa Street Madison, Wisconsin

WELL/ POINT ID	FORMATION	SCREENED INTERVAL (ft bgs)	SAMPLE AND REPORTING FREQUENCY	ANALYTE/ ANALYSIS
MW-4S	Unconsolidated/ Upper Lone Rock	35-50	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-4D	Lower Lone Rock	65-70	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-6S	Unconsolidated/ Upper Lone Rock	31-41	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-11S	Unconsolidated	24-34	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-24	Upper Lone Rock	30-40	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-28	Unconsolidated	28-38	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-29S	Unconsolidated	25-35	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS
MW-29D	Upper Lone Rock	45-50	Semi-annual	PCBs, EPA SW-846 Method 8082; TSS, TDS



# Appendix A Boring Logs, Monitoring Well Development Forms, Well Abandonment Forms, and Well Construction Forms

## **Table of Contents**

- Boring Logs
- Monitoring Well Development Forms
- Well Abandonment Forms
- Well Construction Forms

**Boring Logs** 

State of Wisconsin Department of Natural Resources

#### SOIL BORING LOG INFORMATION

Form 4400-122 Rev. 7-98

			Ro		ed/Wastewater   tion/Redevelopment	Waste I	_	ement								
													Pag	e 1	of	2
	y/Proje					License/			ring Nı	ımber		Boring		er		
	dison Drille			f crew chief (first, la	st) and Firm	02-13 Date Dri				Da	te Drilli	ng Con	npleted	IVIV	V-29   Drill	ing Method
Cra	ig Pla	nt			- 9								•		ro	tary (air or
	und S			DNR Well ID No.	Common Well Name	e Final Sta		5/2018 ter Leve	1	Surfac	e Elevat	1/15/2	2018	Ro		Diameter
	VS	8878			MW-29D			et MS		8	375.9 1	Feet N				inches
Local State	Grid Oi Plane	rigin	(es	stimated: $\square$ ) or $N$	Boring Location   I, E S/C/N	Lat Local				Local C	Grid Loc		r			
SW		of S	W 1	/4 of Section 5,	T 7 N, R 10 E	Long		o 				Feet	□ N □ S			☐ E Feet ☐ W
Facilit	y ID 12532	20		County		County Co	de	Civil To Madi		ity/ or V	Village					
San		20		Dane		13		Madi	SOII			Soil	Prope	erties		
	_	ro	   #	Se	oil/Rock Description						0		liopt			
_ e	Att.	ount	n Fe	An	d Geologic Origin For		S		д		ssive h	e		ξ <sub>2</sub>		nts
Number and Type	Length Att. & Recovered (in)	Blow Counts	Depth In Feet		Each Major Unit		SC	Graphic Log	Well Diagram	PID/FID	Compressive Strength	Moisture Content	Liquid Limit	Plasticity Index	200	RQD/ Comments
Z E	7 %	B	Ā	TOPSOIL, organic	c rich, black, no odor		n	77. 77. Q 7			\(\frac{1}{2}\)	Σŏ	<u> </u>	Pl	Ь	2 0
			-					1/ 1/1/								
			_2	SILTY LEAN CL	AY (CL), slight plasticity,	vellowish										
1 🛭	24		_	brown (10YR 5/6), stiff going to soft w	no odor, dry going to moist	at 3.5' bgs,				0.0	2					3-5
1 SS	24		_4				CL									
2	24		_							0.0	1.25					5-7
2 SS	24		-6							0.0	1.23					
			_		<b>D</b> (ML), fine grained, yello no odor, dry, loose.	wish	ML									
3 SS	24 24		-8	SILTY LEAN CL	AY (CL), slight plasticity, y no odor, moist, soft.	yellowish	CL			0.0	1.25					7.5-9.5
			_	SAND WITH SIL	T (SP), fine grained, trace g 0YR 5/6), no odor, dry, loos	gravel,										
4	24		-10	yenowish brown (1	0 1 K 3/0), 110 Odor, dry, 100.					0.0						10-12
ss	18		_							0.0						10 12
			- 12	sand with silt, same	a ac ahovo											
5 SS	24 18		_	Sund With Sht, Sund	as above.					0.0						12.5-14.5
33	10		- 14				SP									
6 7	24		[							0.0						15-17
6 SS	12		- 16							0.0						13-17
			_	sand with silt, same	a ag abaya											
7 SS	24 12		- 18	Sand with Sitt, Sanit	e as above.					0.0						17.5-19.5
ا دد	12															
<u> </u>			-20													
hereb	y certi	fy that t		rmation on this form	is true and correct to the b	est of my kr	nowled	ge.								
Signat	ure			Waley Burn		RC Enviro										608-826-3600
				01	70	8 Heartland	rail S	uite 300	0 537	17					Fax:	608-238-7156

This form is authorized by Chapters 281, 283, 289, 291, 292, 293, 295, and 299, Wis. Stats. Completion of this form is mandatory. Failure to file this form may result in forfeiture of between \$10 and \$25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be be used for any other purpose. NOTE: See instructions for more information, including where the completed form should be sent.

Form 4400-122A

Boring Number	MV	V-29D Use only as an attachment to Form 4400-1	22.					Pag	ge 2	of	2
Sample							Soil	Prope	erties		
Number and Type Length Att. & Recovered (in) Blow Counts	eet	Soil/Rock Description				ve					
er 7pe 1 Att ered	In F	And Geologic Origin For	S	ic I		ressi	are at	_	ity		ents
Number and Type Length Att. & Recovered (ir	Depth In Feet	Each Major Unit	SC	Graphic Log Well Diagram	PID/FID	Compressive Strength	Moisture Content	Liquid Limit	Plasticity Index	P 200	RQD/ Comments
8 24 B	<u> </u>	SAND WITH SILT (SP), fine grained, trace gravel,	D		0.0	\(\frac{1}{2}\)	Σŭ	<u> </u>	Pl	Ь	20-22
8 24 SS 6	E	yellowish brown (10YR 5/6), no odor, dry, loose.			0.0						
	-22										
		sand with silt, same as above, dolostone gravel becoming increasingly more present. Split spoon unable to be									
	-	sand with silt, same as above, dolostone gravel becoming increasingly more present. Split spoon unable to be advanced due to formation stiffness. Drillers switch from 11.25" HSA to 6" air rotary due to difficult drilling conditions.									
	<u></u> 24	conditions.	SP								
	E										
	26										
	-										
	-28										
	F										
	30	<b>BEDROCK</b> , non-competent bedrock encountered at 29' bgs, drillers pull out and advance 11.25" HSA to 29' bgs to avoid boring blow out and collapse during air rotary.									
	30	Cuttings recovered are fine sand and dolostone mixture.									
	<b>+</b>			· · · · · · · · · · · · · · · · · · ·							
	-32										
	E										
	<del>-</del> 34										
	-	bedrock, same as above.									
	36										
	_										
	-38										
	F										
	_40										
	- 10	BEDROCK, sandstone, drillers indicate bedrock has become more competent then 29-39' bgs.									
	-										
	-42										
	-										
	<del> 44</del>										
	F	bedrock, same as above.									
	_46										
	-										
	-48										
	E										
	50										
		Boring terminated at 50.5' bgs (1/15/2018).									

State of Wisconsin Department of Natural Resources

#### SOIL BORING LOG INFORMATION

Form 4400-122 Rev. 7-98

			Ro	oute To:	Watershed/V				_	ement								
					Remediation	/Redevelopment 🛚	(	Other										
D 114	/D :	, NI					T -	/IC	• • • •	N	· N	1		D .	Pag		of	2
	y/Projec dison						I .	cense/F 02-13-		Monito 114	ring Ni	ımber		Boring	Numbe		W-29	S
				f crew chie	ef (first, last)	and Firm		ate Dril				Da	te Drilli	ng Con	npleted	1111		ing Method
Cra	ig Pla und S	nt							1/16	/2018				1/16/2	) 11 Q			llow stem
	ique W			DNR W	/ell ID No.	Common Well Nam	ne Fii	nal Stat		ter Leve	el	Surfac	e Elevat		2010	Во	rehole	ger Diameter
	VS	879				MW-29S					376.0 1					inches		
Local State	Grid Or	igin	(es	stimated:	O or Bo	ring Location   E S/C/N		Lat	+	0	•	"	Local C	erid Loc				
SW		of S	W 1	/4 of Sect		T 7 N, R 10 H	E	Long '						Feet	□ N □ S		]	☐ E Feet ☐ W
Facilit	y ID				County			nty Coo	de	Civil To		ity/ or V	Village					
	12532	.0		1	Dane		13			Madi	son		Τ	Cail	Dana			
San	nple				Daala Daanintian									Prope	rues			
	tt. & d (in	ınts	Feet			Rock Description deologic Origin For							ive					S
ber ype	th A	Cor	] In			ich Major Unit			CS	hic	am	l e	oress gth	ture	<del>و</del>	city		/ ment
Number and Type	Length Att. & Recovered (in)	Blow Counts	Depth In Feet		2.0	on major om			OS (	Graphic Log	Well Diagram	PID/FID	Compressive Strength	Moisture Content	Liquid Limit	Plasticity Index	P 200	RQD/ Comments
_ 8	I		-			o 35' bgs, see MW-29	D log fo	or		77.77		-	0 01	20	I	I		<u> </u>
				litholog	y.					1/2 2/1/2								
			_2															
			_															
			<u>-</u> 4						CL									
			-						CL									
			_ 6															
			_						ML									
			<del>-</del> 8						CL									
			_															
			-10															
			- 12															
			<u>-</u>															
			14 						SP									
			-16															
			_															
			- -18															
			F															
			_ 															
herek	v certif	v that		rmation or	n this form is:	true and correct to the	hest of	my kn	owled	ge.	<u> </u>							
Signat	-	y mai								ital Co	rnore	tion					Tale	608-826-3600
Malak Bay									uite 300								508-826-3600	

This form is authorized by Chapters 281, 283, 289, 291, 292, 293, 295, and 299, Wis. Stats. Completion of this form is mandatory. Failure to file this form may result in forfeiture of between \$10 and \$25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be be used for any other purpose. NOTE: See instructions for more information, including where the completed form should be sent.

Form 4400-122A

Borin	g Numb	er	MW	V-29S Use only as an attachment to Form 4400-	122.						Pag	ge 2	of .	2
San	nple									Soil	Prope	erties		
	& in)	ro	<del> </del>	Soil/Rock Description					0					
0	vtt. e	unts	Fee	And Geologic Origin For					Sive					ıts
ber ype	th A	သိ	h In	Each Major Unit	CS	hic	ram	Æ	pres	ture	ъ "	icity		/ men
Number and Type	Length Att. & Recovered (in)	Blow Counts	Depth In Feet	Duen mayor ome	S	Graphic Log	Well Diagram	PID/FID	Compressive Strength	Moisture Content	Liquid Limit	Plasticity Index	P 200	RQD/ Comments
<u>8</u> ×	l w	<u> </u>	Д	Boring blind drilled to 35' bgs, see MW-29D log for	n	0 1		Ь	S	20		P Iı	Ь	
			F	lithology.										
			F											
			-22											
			-											
			-24											
			_		SP									
			_											
			_26											
			_											
			- 28											
			- 20											
			_											
			30											
			_											
			- -32											
			_											
			-34											
			F			:::::								
				Boring terminated at 35 feet bgs (1/16/2018).										

**Monitoring Well Development Forms** 

State of Wisconsin Department of Natural Resources

# **MONITORING WELL DEVELOPMENT** Form 4400-113B Rev. 7-98

Route To: Watershed/W		Waste Management L				
	Redevelopment 🛛	Other				
Facility/Project Name	County		Well Name			
Madison Kipp Corp		Dane			/-29D	
Facility License, Permit or Monitoring Number	County Code	Wis. Unique Well Nu		DNR Well	Number	
02-13-578014	13	VS87	78			
1. Can this well be purged dry?	☐ Yes ⊠ No	11. Depth to Water	Before Dev	elopment	After Developme	nt_
Well development method:    surged with bailer and bailed    surged with bailer and pumped	□ 41 □ 61	(from top of well casing)	a.	31.10 ft.	31.97	ft.
surged with block and bailed surged with block and pumped	□ 42 □ 62	Date	b. 1/18	/2018	1/18/2018	
surged with block, bailed, and pumped compressed air bailed only	□ 70 □ 20 □ 10	Time		10:30 □ p	o.m. 03:15	-
pumped only pumped slowly otherSurged Pump and Pumped	□ 5 1 □ 5 0 ⊠	<ul><li>12. Sediment in well bottom</li><li>13. Water clarity</li></ul>		.3 inches	0.0 inch Clear □ 20	ies
3. Time spent developing well	120 min.		Turbid ⊠ (Describe) Brown	1 5	Turbid ⊠ 25 (Describe) Light brown	
4. Depth of well (from top of well casing)	52.0 ft.		Diowii		Light blown	_
5. Inside diameter of well	2.03 in.					_
Volume of water in filter pack and well casing	8.07 gal.					_
7. Volume of water removed from well	110.0 gal.	Fill in if drilling fluids  14. Total suspended	s were used and v	vell is at soli mg/l	-	ıg/l
8. Volume of water added (if any)	0.0 gal.	solids		g.		<i>B</i> -
9. Source of water added N/A		15. COD		mg/l	m	g/l
		16. Well developed by	: Person's Name	and Firm		
10. Analysis performed on water added?	☐ Yes ☒ No	Wesley	Braga			
(If yes, attach results)			_			
17. Additional comments on development:		TRC E	nvironmental			
Facility Address or Owner/Responsible Party Address	,					
Name: Mark Sheppard		I hereby certify that the knowledge.	ne above informa	tion is true a	nd correct to the best of	my
Firm: Madison Kipp Corp.		Signature:	hdy long			_
Street: 201 Waubesa St		Print Name: Wesle	ey Braga			_
City/State/Zip: Madison, WI 53704		Firm: TRC	Environmenta	al Corpora	ution	_

State of Wisconsin Department of Natural Resources

# **MONITORING WELL DEVELOPMENT** Form 4400-113B Rev. 7-98

Route To: Watershed/Wastew		Waste Management				
Remediation/Redev		Other				
Facility/Project Name	County	_	Well Name		7. <b>2</b> 00	
Madison Kipp Corp	0 + 0 1	Dane	1		V-29S	
Facility License, Permit or Monitoring Number	County Code	Wis. Unique Well Nur		DNR Well	Number	
02-13-578014	13	VS87	9			
1. Can this well be purged dry?	Yes □ No	11 B 1 W	Before Dev	elopment	After De	velopment
		11. Depth to Water (from top of				
2. Well development method:		well casing)	a.	28.51 ft.		32.85 ft.
surged with bailer and bailed	4 1	wen casing)				
surged with bailer and pumped	61	Data	ե 1/19	3/2018	1/	18/2018
surged with block and bailed	4 2 6 2	Date	b. 1/18	5/2010	1/ .	10/2010
surged with block and pumped surged with block, bailed, and pumped	70			₩ -		
compressed air	2 0	Time	c.	⊠ a 10:35 □ p		□ a.m. 02:45 ⋈ p.m.
bailed only	1 0	Time	C.	10.55 🗆 р	7.111.	02.43 ⋈ p.m.
pumped only	5 1	12. Sediment in well	(	0.0 inches		0.0 inches
pumped slowly	5 0	bottom		.o menes		o.o menes
other Surged Pump and Pumped		13. Water clarity	Clear	1 0	Clear ⊠	2 0
onici		13. Water chartey		1 5	Turbid	2 5
3. Time spent developing well	120 min.		(Describe)		(Describe)	
3. Time spent developing wen	120 11111.		Brown		None	
4. Depth of well (from top of well casing)	36.2 ft.		Brown		110110	
2 span of won (from top of wen such say)	20.2 1					
5. Inside diameter of well	2.03 in.					
6. Volume of water in filter pack and well						
casing	8.80 gal.					
		Fill in if drilling fluids	were used and	well is at soli	id waste facili	ty:
7. Volume of water removed from well	35.0 gal.					
		14. Total suspended		mg/l		mg/l
8. Volume of water added (if any)	0.0 gal.	solids				
9. Source of water added N/A		15. COD		mg/l		mg/l
5. Source of water daded						
10. Analysis performed on water added?	Zag ⊠ Na	16. Well developed by:	Person's Name	e and Firm		
(If yes, attach results)	Yes ⊠ No	Wesley	Braga			
(11 yes, attach results)		TRC En	vironmental			
17. Additional comments on development:				<u> </u>		<del></del>
Facility Address or Owner/Responsible Party Address		I hereby certify that the	a above informs	ntion is true o	nd correct to t	the best of my
		knowledge.	e above iiiioiiiia	mon is mue a	ilia collect to	the best of my
Name: Mark Sheppard			11	10		
Firm: Madison Kipp Corp.		Signature:	Wishy	Bur		
1 mm				-		
Street: 201 Waubesa St		Print Name: Wesle	y Braga			
City/State/Zip: Madison, WI 53704		Firm: TRC I	Environment	al Corpora	ation	
		1 11111.		F		

**Well Abandonment Forms** 

State of Wis., Dept. of Natural Resources dnr.wi.gov

3671 Monroe Rd.

City

DePere

## Well / Drillhole / Borehole Filling & Sealing

Form 3300-5 (R 4/2015)

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return this form to the appropriate DNR office and bureau. See instructions on reverse for more information. Route to DNR Bureau: Verification Only of Fill and Seal **Drinking Water** Watershed/Wastewater Remediation/Redevelopment Waste Management Other 1. Well Location Information 2. Facility / Owner Information County WI Unique Well # of Hicap # Facility Name Madison Kipp Corp Dane (MW-22D) acility ID (FID or PWS) Lattitude / Longitude (see instructions) Format Code Method Code 113125320 ⊠ DD **GPS008** License/Permit/Monitoring # SCR002 ☐ DDM OTH001 02-13-578014 1/4 / W 1/4 SW Section Township Range Original Well Owner 10 or Gov't Lot # W Madison Kipp Corp. Well Street Address resent Well Owner Mark Sheppard 201 Waubesa St Mailing Address of Present Owner Well City, Village or Town Well ZIP Code 201 Waubesa St Madison 53704 City of Present Owner State ZIP Code Subdivision Name Lot# WI 53704 4. Pump, Liner, Screen, Casing & Sealing Material Reason For Removal From Service WI Unique Well # of Replacement Well Pump and piping removed? N/A Well Decomission 3. Filled & Sealed Well / Drillhole / Borehole Information Liner(s) removed? Yes No N/A Yes X Original Construction Date (mm/dd/yyyy) Liner(s) perforated? No N/A Monitoring Well X 01/05/2013 Screen removed? Yes No N/A Water Well X Casing left in place? Yes No N/A If a Well Construction Report is Borehole / Drillhole Was casing cut off below surface? Yes No N/A available, please attach. Did sealing material rise to surface? Yes No N/A Construction Type: Did material settle after 24 hours? Yes X No N/A □ Drilled Driven (Sandpoint) Dug If yes, was hole retopped? No N/A Other (Specify) If bentonite chips were used, were they hydrated Formation Type: with water from a known safe source Yes No N/A Required Method of Placing Sealing Material Unconsolidated Formation Bedrock Conductor Pipe-Gravity Total Well Depth From Ground Surface (ft) Conductor Pipe-Pumped Casing Diameter (in.)  $\boxtimes$ Screened & Poured (Bentonite Chips) Other (Explain) 50.0 2.03 Lower Drillhole Diameter (in.) Sealing Materials Casing Depth (ft.) Neat Cement Grout 8.0 Concrete 45.0 Sand-Cement (Concrete) Grout Bentonite Chips Yes Was well annular space grouted? No Unknown For Monitoring Wells and Monitoring Well Boreholes Only: If yes, to what depth (feet)? Depth to Water (feet) Bentonite Chips Bentonite - Cement Grout Granular Bentonite Bentonite - Sand Slurn 5. Material Used to Fill Well / Drillhole No. Yards, Sacks Sealant Mix Ratio From (ft.) To (ft.) or Volume (circle one) or Mud Weight 3/8" Hole Plug Surface 50.0 1.09 cubic feet 6. Comments MW-22D 7. Supervision of Work DNR Use Only Name of Person or Firm Doing Filling & Sealing License # Date of Filling & Sealing or Verification Date Received Noted By (mm/dd/yyyy) Ground Source 01/16/2018 Street or Route

Telephone Number

920.336.3659

State

WI

ZIP Code

54115

Signature of Person Doing Work

Comments

Date Signed

2-2-18

State of Wis., Dept. of Natural Resources dnr.wi.gov

#### Well / Drillhole / Borehole Filling & Sealing

Form 3300-5 (R 4/2015)

Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved, form to the appropriate DNR office and bureau. See instructions on reverse for more information.

□ Verification     □ Ve	on Only of F	ill and S	eal		to DNR Burea Drinking Water	r			ed/Wastew	vater	⊠ R	emedia	ition/Red	levelop	ment
4 14/-111	1.5			LUV	Vaste Manage	emen		Other							
1. Well Location	NAME AND ADDRESS OF TAXABLE PARTY.	ue Well # of		Hicap #			2. Facility / Facility Name	Owner In	tormatic	on					
County	Remove			i noup ii			Madison K	inn Corn							
Dane		(W-22S)					Facility ID (FID		_						
Lattitude / Longitu		ns)		t Code DD	Method Cod		113125320	)							
0	N		1000	DDM	SCR002	2	License/Permi	t/Monitoring	#	14					
1/4/1/4 SW	W SW	Section		Township	Range	1	02-13-578								
or Gov't Lot #	/4 SVV	36010		7	10	E	Original Well C								
Carl Committee and the					"	W	Madison K Present Well C		-						
Well Street Address	SS						Mark Shep	ENINONE DE				11			
201 Waubesa	TE 171.70						Mailing Addres		t Owner						
Well City, Village	or Town			Well ZIF	Code		201 Waub								
Madison				5370	4		City of Present	t Owner				State	ZII	Code	,
Subdivision Name	9			Lot #			Madison					WI		53704	
Reason For Remo	oval From Service	WI Uniqu	ue Well	# of Replac	cement Well		4. Pump, Li	ner, Scree	en, Casir	ng & S	Sealing Mat	erial			
Well Decomis		oraq		or replac	SOME THE		Pump and p	piping remov	ved?			Yes	☐ No		N/A
3. Filled & Sea		hole / Bore	hole I	nformatio	on		Liner(s) ren	noved?				Yes	☐ No		N/A
Monitorin	ng Well	Origina	al Const	ruction Dat	te (mm/dd/yyy	y)	Liner(s) per					Yes	□ No		N/A
☐ Water W		01/	05/2013	3			Screen rem					Yes	No.		N/A N/A
		If a	Well Co	nstruction I	Report is		Casing left	in place?				res	_ No	,	N/A
Borehole	/ Drillhole			ease attac			-	cut off belo				Yes	No.		N/A
Construction Type	e:						1. Salary 1. Sal	material rise				Yes	□ No		N/A N/A
Drilled	D	riven (Sandp	oint)		Dug		TOTAL TOTAL STATE OF THE STATE	I settle after as hole retor		?	-	Yes	N No		N/A
Other (Specif	fy)						THE PARTY NAMED IN COLUMN TWO	chips were	28.03.2000VM	e they	hydrated	100			IVA
Formation Type:							with water f			-	nyaratoa _	Yes	☐ No		N/A
Unconsolidate	ed Formation			Bedrock			Required Meth	nod of Placir tor Pipe-Gra	The second second	Mater		-t Di			
Total Well Depth F 35.0	From Ground Surf	face (ft) C	asing Di 2.03	iameter (in.	.)		Screene	ed & Poured ite Chips)			Other		oe-Pump n)	ea	
Lower Drillhole Dia	ameter (in.)	C	asing D	epth (ft.)			Sealing Materi	als							
8.0			25.0					ment Grout			and the same of th	ncrete			
Was well annular	snace arouted?	⊠ Yes	П	No	Unknown			ement (Cond				ntonite	Chips		
If yes, to what dep			to Wate		Onknown		For Monitoring  Bentonit		Monitorin	g Well	and the same of	(5)	0 .		
21.0	, (100t).	28.5		1 (1001)				r Bentonite		H	Bentonite - S				
5. Material Use									No V	arde	Sacks Sea	Contract of the last	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Owner,	x Rat	io
5. Material Use	ed to Fill Well /	Drilinole	ul-en e				From (ft.)	To (ft.)			e (circle on			ud We	
3/8" Hole Plug	g					g	Surface	35.0		0.76	cubic feet				
6. Comments															
MW-22S															
7. Supervision											DNI	R Use	Only	Coll Dis	
Name of Person or	r Firm Doing Filling	g & Sealing		License	#	Da	te of Filling & S	Sealing or Ve	erification	Date F	Received		oted By		
Ground Source	e					(m	m/dd/yyyy)	01/16/201	The speciment						
Street or Route						Te	lephone Numb	er		Comm	ents				
3671 Monroe I	Rd.				THE C		920.336.3659								
				State WI	ZIP Code 54115		Signature of Po	erson Doing	Work			Da	ate Sign		13

State of Wis., Dept. of Natural Resources

# Well / Drillhole / Borehole Filling & Sealing Form 3300-5 (R 4/2015) Page 1 of

Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved, form to the appropriate DNR office and bureau. See instructions on reverse for more information.

☐ Verification C	only of Fill	and S	eal		to DNR Burea Drinking Water			Watershe	d/Wastewa	er [	⊠ R	emedia	ation/Re	develop	oment
					Waste Manage	_		Other							
1. Well Location Info			E PA	是新的特点的	<b>出版的</b> 新聞		2. Facility		formation	Single Police	a de la composición della comp				
County	WI Unique V Removed W			Hicap #		F	acility Name							TATE	
Dane	(MW-2	23D)				-	Madison I		1000						
Lattitude / Longitude (see	e instructions)			t Code	Method Code	9	acility ID (FIII				- =				
0	N		1000	DD	☐ GPS008 ☐ SCR002		icense/Perm		#		-				
0	W			DDM	OTH001		02-13-578								
1/4 SW 1/4	SW	Section	Т	ownship	Range	E	Original Well		1						
or Gov't Lot #		5		7	10 =	w	Madison F	Cipp Corp.							
Well Street Address						P	resent Well (	Owner							
201 Waubesa St							Mark Shep	_							
Well City, Village or Town	n			Well ZIF	Code	N	Mailing Addre	ss of Present	t Owner						
Madison				5370			201 Waub								
Subdivision Name				Lot #	7		ity of Presen	t Owner				State	8111	P Code	
							Madison		WI		53704				
Reason For Removal Fro	om Service	WI Uniqu	e Well	# of Replac	cement Well	- 4	l. Pump, Li	Mate							
Well Decomission								piping remov		Yes	□ N		N/A		
3. Filled & Sealed W	ell / Drillhole						Liner(s) ren			Yes	□ N		N/A		
Monitoring Well		100000			te (mm/dd/yyyy	()	Liner(s) per Screen rem		H	Yes	N		N/A		
Water Well		01/0	3/2013	3		_	Casing left			Yes	N		N/A N/A		
Borehole / Drillh	olo	lf a V	Vell Cor	nstruction I	Report is								H PRODUCE LEI		
Borenole / Drilin	ole	avail	able, pl	ease attacl	h.		Was casing		Yes	N		N/A			
Construction Type:							Total Control of the Control	material rise		Yes	N		N/A		
Drilled	Driven	(Sandpo	int)		Dug			I settle after			H	Yes	N		N/A N/A
Other (Specify)							The state of the s	as hole retop chips were u	• • • • • • • • • • • • • • • • • • • •	hov budrata		165	∐ N		IVA
Formation Type:								rom a known				Yes	$\square$ N		N/A
Unconsolidated Form	nation		⊠ F	Bedrock		R	equired Meth								
							Conduc	tor Pipe-Grav			Conduc	tor Pir	e-Pum	ped	
Total Well Depth From G	round Surface (		975.8	ameter (in.	.)		Screene	d & Poured			A CONTRACTOR OF THE PARTY OF TH	Explair			
50.0		_	2.03					ite Chips)			100				
Lower Drillhole Diameter	(in.)	Ca	sing De	epth (ft.)		0	ealing Materi				7				
8.0		- 4	15.0					ment Grout			7	ncrete			
Was well annular space of	grouted?	X Yes		No 🗌	Unknown	F	or Monitoring	ement (Conc		No!! Baraha		tonite	Chips		
If yes, to what depth (feet	1)?	Depth to	Water	r (feet)		-1	Bentonit		vioriitoring	Bentoni			Grout		
41.0		27.7						r Bentonite		Bentoni	4.	100000			
5. Material Used to F	ill Wall / Dril	Ibolo						Market 1	No. Yar	ds, Sacks			William State	x Rati	^
	III VVCII / DIII	inole					From (ft.)	To (ft.)		ume (circ				ud We	
2/9" Hala Dha								400							
3/8" Hole Plug		_				_	Surface	50.0	1.	09 cubic f	eet				
						-									
6. Comments											- Callelland		Paris t		SAID THE
MW-23D													No. of Co.		
7. Supervision of Wo				188 355		V. Taranta				Ziner:	DNR	Use	Only		
Name of Person or Firm D	oing Filling & S	ealing		License	#	Date	of Filling & S	Sealing or Ver	rification Da	te Received	1		ted By		
Ground Source Street or Route							(dd/yyyy)	01/16/2018							
3671 Monroe Rd.						Telephone Number Comments									
City			I	State	ZIP Code		0.336.3659		10/1-			1=			
DePere			1	WI	54115	Ol	gnature of Pe	00	Work				te Signe	_	0.
				44.1	34113	_		-					2-		0
							U								

## State of Wis., Dept. of Natural Resources dnr.wi.gov

# Well / Drillhole / Borehole Filling & Sealing Form 3300-5 (R 4/2015) Page 1 of 2

Notice: Completion of this report is required by chs. 160, 281, 283, 289, 291-293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291-293, 295, and 299, Wis. Stats., failure to file this form may result in a forfeiture of between \$10-25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on this form is not intended to be used for any other purpose. Return this form to the appropriate DNR office and bureau. See instructions on reverse for more information.

to the appropriate Div	N office and bu	reau. S	ee instr				ion.										
Varification On	to DNR Burea																
Verification Or	ily of Fill a	ina Se	eai		Drinking Water			Watershe	ed/Waste	ewater >	☑ R	emedi	ation/Red	levelopm	ent		
					Waste Manage	ement		Other						and the same of th			
1. Well Location Info	rmation		75 B. S.	all re		2. Fac	ility	/ Owner In	format	ion		100	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Salar St.			
County	WI Unique W		307	Hicap #		Facility I											
D	Removed We					Madi	son	Kipp Corp									
Dane Lattitude / Longitude (see	(MW-2:	-	_		Tea a second	Facility I		D or PWS)							_		
o cattitude / Longitude (see			Format		Method Code  GPS008		2532	20									
0	N		100	DDM	SCR002			nit/Monitoring	#								
	W				OTH001	02-13	3-57	8014									
1/4 SW 1/4 S	SW	Section	T	ownship	Range 🖂	E Original											
or Gov't Lot #		5		7	10	COLUMN TO A STATE OF THE PARTY	son	Kipp Corp.									
Well Street Address						Present											
004 14/- 1 0/		.				Mark	She	ppard									
201 Waubesa St Well City, Village or Town		_		T				ess of Presen	t Owner				-				
				Well ZIF		The second secon		oesa St									
Madison Subdivision Name				5370	4			nt Owner				State	ZIF	Code	_		
Subdivision Name				Lot #		Madi								53704			
Reason For Removal From	Sonia- III	/I I below	- 14/- 11 /	1-15			4. Pump, Liner, Screen, Casing & Sea					WI 53704 ling Material					
	i Service   W	/I Unique	e vvell #	of Repla	cement Well	The state of the s	Pump and piping removed?					Yes	☐ No	N 1	WA.		
Well Decomission	II / Deilli1	/ D	-1-1			The state of the s		moved?	eur		H	Yes	No No	-	WA WA		
3. Filled & Sealed We								erforated?			H	Yes	No No		WA WA		
Monitoring Well		10/2/20 (7.10)		uction Da	te (mm/dd/yyyy			noved?			H	Yes	No No		WA WA		
Water Well		01/03	3/2013			2000		in place?			X	Yes	No No		WA WA		
Borehole / Drillhole	•			struction		- 00311	a lett	iii piace (							WA		
Boreriole / Drillinois	е	availa	ble, ple	ase attac	h.			g cut off below				Yes	No	N	N/A		
Construction Type:						Did se	ealing	material rise	ace?	$\boxtimes$	Yes	☐ No		N/A			
Drilled	Driven (	Sandpoi	int)	Г	Dug	Did m	ateria	al settle after	24 hours	5?		Yes	No	N	V/A		
Other (Specify)					_ ,			as hole retop				Yes	☐ No	≥ v	N/A		
										ere they hydrated			_	-			
Formation Type:								from a known				Yes	No	N N	V/A		
Unconsolidated Forma	ition		В	edrock		Required	Met	hod of Placing	g Sealing	g Material							
Total Well Depth From Gro	und Surface (ft	Cas	ing Dia	meter (in.	1			ctor Pipe-Grav	vity	Co	nduc	or Pi	e-Pumpe	ed			
35.0	and Garrace (it		10.70	meter (m.	.)	⊠ Sc	reen	ed & Poured nite Chips)		Ot	her (	Explain	n)				
The state of the s	- 1	_	.03			Sealing N			1								
Lower Drillhole Diameter (in	1.)	Cas	ing Dep	oth (ft.)													
8.0		2	5.0					ement Grout				crete					
Was well annular space gro	outed?	Yes		No 🗌	Unknown			ement (Conc					Chips				
If yes, to what depth (feet)?		Depth to			OTIKITOWIT				Monitorii	ng Well Borehole							
21.0		27.5	rrator	(1001)				te Chips		Bentonite							
	A CONTRACTOR			Territoria	MANUSIPI OF STREET	L Gr	anula	r Bentonite		☐ Bentonite	A CONTRACTOR		irry	NACOTOR DE MINIS			
5. Material Used to Fil	I Well / Drillh	nole				From (	ft.)	To (ft.)		Yards, Sacks S Volume (circle			Mix	Ratio			
							Description of the last		OI	volume (circle	one	)	or Mu	d Weig	nt		
3/8" Hole Plug						Surfa	ce	35.0		0.76							
						Surfa	LE	35.0	-	0.76 cubic fee	et						
									-								
6. Comments			e zalite		72322232					And the source of the source o		250	anviet	September 1	2011		
MW-23S				A STANSFORM						ANT STATE OF THE STATE OF							
7. Supervision of Worl	k	I NE S	7 5 5 5 5	ELECTIVE ST					District Control								
Name of Person or Firm Doi	ing Filling & Sea	aling		License	#	Date of Filling	0.00	Cooling or V	different!	Data D	JNR	Use			ide .		
Ground Source	g			Licerise		(mm/dd/yyyy	y & S			Date Received		No	ted By				
Street or Route								01/16/2018	3			$\perp$					
3671 Monroe Rd.						Telephone N				Comments							
City			0	tate	ZIP Code	920.336.			AI .								
DePere			3			Signature	OFP	erson Doing	Vork			Da	te Signed				
				WI	54115	(	1	y Phi	-		2-2-78						
								0							_		

**Well Construction Forms** 

State of Wisconsin Department of Natural Resources								
Route To:		astewater □ Redevelopment ⊠	Waste Man	nagement	MONITORING WELL Form 4400-113A	L CONSTR Rev. 7-9		ΓΙΟΝ
Facility/Project Name	Local Grid Loc	ation of Well			Well Name			
Madison Kipp Corp		ft.	ft	□ E.	MW	-29D		
Facility License, Permit or Monitoring No.	Local Grid Orig	zin (estimated:	) or W	U W. ∕ell Location ⊠	Wis. Unique Well No.	DNR Well 1	Jum	hor
02-13-578014	I at				VS878	DIVIC WOIL	vuiii	UCI
Facility ID	l	_			Date Well Installed	L		
·		ft. N,		_ ft. E. S/C/N				
113125320 Type of Well		on of Waste/Source		<b>53.</b> F	01/15	5/2018		
	SW 1/4 of	SW 1/4 of Sec. 5	. T. 7	NR 10 □W	Well Installed By: (Per	son's Name a	nd F	irm)
Well Code 12/pz Distance from Waste/ Enf. Stds.	Location of We	ell Relative to Waste/So	urce	Gov. Lot Number	Craig	Plant		
Source Apply	u 🗆 Upgrad	lient s □ Sid	egradient	2011 2011 (11111001	G			
II.	d 🛛 Downg			. Cap and lock?	Ground	Source	=	<del></del>
	ft. MSL			. Protective cover p	ine:	⊠ Ye	3 ∐	No
B. Well casing, top elevation 87	7.61 ft. MSL		<b>\</b> /'	a. Inside diameter:	•		4	in.
C. Land surface elevation 87	75.86 ft. MSL			b. Length:		-	7	<u>'.0</u> ft.
C. Land surface elevation	<u>σ.σο</u> π. MSL		200	c. Material:		- C. 1		
D. Surface seal, bottom 874.9 ft. MSL	or1.0 ft.		TE VIEW	c. Material:		Steel		
12. USCS classification of soil near screen:			X16 216 21	d. Additional prote		Other		
	v =			•		☐ Yes	; ⊠	No
	W□ SP□ □ CH□			If yes, describe:			_	
Bedrock ⊠	Zu Chu		3	. Surface seal:		Bentonite	$\boxtimes$	3 0
	s 🖾 No					Concrete		19070
•						Other		obusas obusas
	y ⊠50		`4.	. Material between	well casing and protectiv	e pipe:		
Hollow Stem Auge	F14 1100					Bentonite	$\boxtimes$	3 0
HSA to 29' bgs Othe	er 🛛 🚐					Other		10000 10000
			5.	. Annular space sea	l: a. Granular/Chipp	ed Bentonite	П	3 3
_	ir ⊠ 0 1	l		-	ud weight Bentonit			
Drilling Mud □ 0 3 Non	e □99		c	c11Lbs/gal m	ud weight Ber	tonite slurry	×	3 1
16 70 70 10 10				l% Benton		cement grout		
16. Drilling additives used?   ⊠ Ye	s 🗆 No		e	e. 20.08 Ft <sup>3</sup>	volume added for any of	the above		5 0
	÷		1	f. How installed:		Tremie		0.1
DescribeN/A						mie pumped		-
17. Source of water (attach analysis, if required	):					Gravity		
None			6	. Bentonite seal:	a Rento	nite granules		
		, 🔘 🕅	/ 0.		a. Bento 3/8 in. □ 1/2 in. Be	nte granules		22
E. Bentonite seal, top 842.9 ft. MSL	or33.0	f. 🛭		°C.	ло III. — 1/2 III. — Ве			
2. 201101110 0001, top 1t. 141517 (		"`\	/ 7		: Manufacturer, product			
F. Fine sand, top <u>834.9</u> ft. MSL of	or 41.0	a . 🔪 🔉 🕅			40/60 Badger	name & mes	11 3121	*******
1. The said, top	DI	ft.		a b. Volume added	0.35 ft	3	_	irdidos irdidos
G. Filter pack, top 832.9 ft. MSL of	or43.0				11			
G. Filter pack, top	or	ft. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	/ /°.	. Filter pack materia	l: Manufacturer, produc	t name & me	sh siz	
II Samoon is int ton 830.7 G MGI	or45.2			a	20/40 Badger			innia d
H. Screen joint, top 830.7 ft. MSL of	or	ft.		b. Volume added	ft			
825.7 0.355	50.2		/ 9.	Well casing:	Flush threaded PVC			2 3
I. Well bottom 825.7 ft. MSL of	or50.2	ft. <			Flush threaded PVC	schedule 80		24
005.4	<b>50.5</b>		_			Other		1.25
J. Filter pack, bottom 825.4 ft. MSL of	or50.5	ft \	10.	Screen material:	Sch 40 PVC	2		aideda ( adada)
		111111		<ul><li>a. Screen Type:</li></ul>		Factory cut		11
K. Borehole, bottom825.4 ft. MSL of	or50.5	ft			Co	ntinuous slot	$\boxtimes$	0 1
		\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				Other		344
L. Borehole, diameter6.0 in.		V////X	\	b. Manufacturer	Johnson Screens	3		
				c. Slot size:			0.01	0_ in.
M. O.D. well casing 2.37 in.				d. Slotted length:			5.0	0 ft.
-			<sup>\</sup> 11.	Backfill material (l	pelow filter pack):	None		
N. I.D. well casing $2.03$ in.						Other		100000
I hereby certify that the information on this form	is true and corre	ect to the best of mv kn	owledge.					
	-	irm TRC Environmen		tion		TI-1 (00	007	2600
Signature		708 Heartland Tr				Tel: 608-		

Please complete both Forms 4400-113A and 4400-113B and return them to the appropriate DNR office and bureau. Completion of these reports is required by chs. 160, 281, 283, 289, 291, 292, 293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291, 292, 293, 295, and 299, Wis. Stats., failure to file these forms may result in a forfeiture of between \$10 and \$25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on these forms is not intended to be used for any other purpose. NOTE: See the instructions for more information, including where the completed forms should be sent.

State of Wisconsin Department of Natural Resources						
Route To:	Watershed/Wastewater Remediation/Redevelopment			MONITORING WEL Form 4400-113A	L CONSTR Rev. 7-9	
Facility/Project Name	Local Grid Location of Well			Well Name		
Madison Kipp Corp	ft. N.  Local Grid Origin (estin	ft.	□ W.	MW	-29S	
Facility License, Permit or Monitoring No.	Local Grid Origin (estin	nated: 🗌 ) or W	ell Location 🖂	Wis. Unique Well No.	DNR Well N	Jumber
02-13-578014 Facility ID	Lat	-		VS879 Date Well Installed		
113125320	St. Plane ft. N Section Location of Waste/Sou	N,	ft. E. S/C/N		10010	
Type of Well			⊠E		/2018 son's Name a	nd Firm)
Well Code 11/mw	SW 1/4 of SW 1/4 of Sec	c5, T7	N, R. <u>10</u> □ W		Plant	ild I illii)
Distance from Waste/ Enf. Stds.	Location of well Kelative to w	/aste/Source  ☐ Sidegradient	Gov. Lot Number	Claig	Гаш	
Source ft. Apply		☐ Not Known		Ground	Source	
A. Protective pipe, top elevation	ft. MSL		. Cap and lock?		⊠ Yes	□ No
B. Well casing, top elevation87	77.80 ft. MSL	\ <sup>2</sup> .	. Protective cover pi	•		40.
	/5.97 ft. MSL <		<ul><li>a. Inside diameter:</li><li>b. Length:</li></ul>		_	4.0 in 7.0 ft.
	<u> </u>		c. Material:		 Steel	π. ⊠ 04
D. Surface seal, bottom 875.0 ft. MSL	orft.	12/2/2			Other	0400-7
12. USCS classification of soil near screen:		AKOKOK	d. Additional prote	ection?	☐ Yes	s ⊠ No
1	V □ SP □		If yes, describe:			_
SM □ SC □ ML □ MH □ CI Bedrock ⊠	СП СНП	3.	. Surface seal:		Bentonite	⊠ 30
13. Sieve analysis attached?	s ⊠ No				Concrete	200
	y □50		Matarial battyroon v	well casing and protectiv		
Hollow Stem Auge	I №	<b>₩</b> **	. Material between v	wen casing and protectiv	Bentonite	⊠ 3.0
	r 🗆 📗					**************************************
		5.	. Annular space seal	: a. Granular/Chipp	ed Bentonite	⊠ 33
	r □01	X1 KXXI	•	ud weight Bentonit		
Drilling Mud □ 0 3 Non	e ⊠99		cLbs/gal m		ntonite slurry	
16. Drilling additives used?  \( \text{Yes}  \text{No} \) \( \text{No} \) \( \text{d.}  \text{% Bentonite} \cdot \text{.}  \text{Bentonite} \cdot \text{Bentonite} \)				cement grout	□ 50	
	eFt' volume added for any of the above					
DescribeN/A		f	f. How installed:	Tea		□ 01 □ 02
17. Source of water (attach analysis, if required)	):			116	mie pumped Gravity	□ 02 □ 08
None		6.	Bentonite seal:	a. Bento	nite granules	
				3/8 in. □ 1/2 in. Be		
E. Bentonite seal, top ft. MSL o	or ft. \					
056.0	•••	7.	Fine sand material:	Manufacturer, product	name & mes	n size
F. Fine sand, top 856.0 ft. MSL of	or		a	40/60 Badger 0.65	2	o Sin Sang
G. Filter pack, top 854.0 ft. MSL of	/ K	7 177 17	b. Volume added	0.65 ft l: Manufacturer, produc		.ae
G. Their pack, top II. WISE C	" 11.	)		20/40 Badger	t name & me	sn size
H. Screen joint, top 851.3 ft. MSL of	or24.6 ft.		a b. Volume added	4.27 ft	3	
		9.	Well casing:	Flush threaded PVC		⊠ 23
I. Well bottom 841.6 ft. MSL of	or <u>34.4</u> ft.		· ·	Flush threaded PVC	schedule 80	
941.0	250				Other	
J. Filter pack, bottom 841.0 ft. MSL of	or35.0 ft.	<b>□</b> 10.	Screen material:	Sch 40 PVC		infinite d
K. Borehole, bottom841.0 ft. MSL of	or <u>35.0</u> ft.		a. Screen Type:	Q.	Factory cut	
R. Botchole, bottom	" 11.			Co	ntinuous slot	
L. Borehole, diameter 8.0 in.			b. Manufacturer	Johnson Screens	Oulei	
,			c. Slot size:			0.010 in.
M. O.D. well casing 2.37 in.			d. Slotted length:		_	10.0 ft.
2.02		`11.	Backfill material (b	pelow filter pack):		□ 14
N. I.D. well casing 2.03 in.					Other	
I hereby certify that the information on this form	is true and correct to the best of	f my knowledge				
Cionotura	Eima	rironmental Corporat	rion		Tol. 600	926 2600
Signature Natural Burn		tland Trail Suite 300				-826-3600 -238-7156

Please complete both Forms 4400-113A and 4400-113B and return them to the appropriate DNR office and bureau. Completion of these reports is required by chs. 160, 281, 283, 289, 291, 292, 293, 295, and 299, Wis. Stats., and ch. NR 141, Wis. Adm. Code. In accordance with chs. 281, 289, 291, 292, 293, 295, and 299, Wis. Stats., failure to file these forms may result in a forfeiture of between \$10 and \$25,000, or imprisonment for up to one year, depending on the program and conduct involved. Personally identifiable information on these forms is not intended to be used for any other purpose. NOTE: See the instructions for more information, including where the completed forms should be sent.

# Appendix B Cap Maintenance Plan



## Cap Maintenance Plan

Madison-Kipp Corporation 201 Waubesa Street Madison, Wisconsin

WDNR BRRTS #02-13-578014

February 2018

Prepared For Madison-Kipp Corporation 201 Waubesa Street Madison, Wisconsin 53704

Prepared By TRC Environmental Corporation 708 Heartland Trail, Suite 3000 Madison, Wisconsin 53717

# **Table of Contents**

1.	Prop	erty and Plan Information	1
	1.1	Site Information	1
	1.2	Contact/Notification Information	1
	1.3	Purpose	1
	1.4	Contamination Description	
	1.5	Notifications	2
	1.6	Amendment or Withdrawal of Cap Maintenance Plan	2
2.	Cap	Maintenance Plan	3
	2.1	Cap Description	
	2.2	Cap Inspection	
	2.3	Maintenance	
	2.4	Prohibited Activities	

## List of Figures

Figure 1 Cap Maintenance Plan Map

Figure 2 Geologic Cross Sections A-A' and B-B'

## **List of Appendices**

Appendix A WDNR Form 4400-305

Appendix B Cap Photo Log

Appendix C Cover Maintenance Plan for BRRTS #02-13-576860 (Arcadis, 2016)

# Section 1 Property and Plan Information

1.1 Site Information

Site Location: 201 Waubesa Street

Madison, WI 53704

Tax Parcel ID #: 251/0710-053-0801-2

WDNR/FID #: 113125320

WDNR BRRTS/Activity #: 02-13-578014

1.2 Contact/Notification Information

Site Owner and Operator: Madison-Kipp Corporation (MKC)

201 Waubesa Street Madison, WI 53704

608-244-3511

Signature: Mark Sheppard

Environmental, Health, and Safety Manager

Consultant: TRC Environmental Corporation

708 Heartland Trail, Suite 3000

Madison, WI 53717

Attention: Katherine Vater, Project Manager

(608) 826-3663

Wisconsin Department of Natural

Resources (WDNR):

Michael Schmoller

3911 Fish Hatchery Road

Fitchburg, WI 53711

(608) 275-3267

#### 1.3 Purpose

This document is the Cap Maintenance Plan (Plan) for the above-referenced site, prepared in accordance with the requirements of s. NR 724.13(2) and 727.05(1)(b)2, Wisconsin

Administrative Code and the Stipulation and Order for Judgment between MKC and WDNR (November 22, 2017). The cap consists of a combination of existing concrete building foundation, and concrete/asphalt pavement. The boundaries of the cap can be seen on Figure 1. The cap protects human health and the environment from the residual PCB (polychlorinated biphenyls) contamination by preventing direct contact with remaining contamination from historical operations on the property.

The property owner will maintain a copy of this Plan and make it available to all interested parties (i.e., WDNR, on-site employees, contractors, future property owners, etc.) for viewing upon request.

### 1.4 Contamination Description

Historical die casting operations that involved hydraulic fluids containing PCBs, and dust suppression of the parking lot using PCB-containing oils at the facility resulted in PCB impacts to soil. Residual contamination from these activities remains on-site in the soil above the NR 720 industrial direct contact residual contaminant levels (RCL) for soil.

The locations of soil known to contain exceedances above their RCLs are shown on Figure 1, and cross sections under the facility floor showing the PCB concentrations in the soil can be seen in Figure 2.

#### 1.5 Notifications

Madison-Kipp Corporation will notify WDNR within 60 days of any planned changes in occupancy, land or property use, or system modifications.

In the event that necessary maintenance activities require limited removals of the cap, MKC will notify workers of potential direct contact exposure hazard.

Restoration of portions of the cap with similar or superior materials (e.g., replacing asphalt with concrete) is allowable, but notification and documentation of the restoration and any change in conditions must be provided by MKC to WDNR upon completion of the repairs.

2

## 1.6 Amendment or Withdrawal of Cap Maintenance Plan

This Plan may not be withdrawn or amended unless approved by WDNR.

### 2.1 Cap Description

The majority of the site is capped with an impermeable surface approximately 3 to 12 inches thick consisting of concrete building foundations, or concrete/asphalt pavement. In particular, the cap being inspected under this maintenance plan is primarily the concrete building floor/foundation. Figure 1 shows the surface features that comprise the cap. Figure 1 also shows the existing cap for BRRTS #02-13-576860, and a copy of that Cap Maintenance Plan is included in Appendix C. Note that these two caps will be inspected separately, as they are associated with separate BRRTS cases.

Photographs of the current conditions of the cap are included in Appendix B. Based on the current and future planned use of the property as a manufacturing facility, the cap should function as intended unless disturbed.

#### 2.2 Cap Inspection

The cap needs to be inspected annually by the property owner or their designated representative. An inspection checklist (WDNR Form 4400-305) is provided in Appendix A.

The inspections will be performed to evaluate damage due to settling, exposure to weather, wear from traffic, or other factors. The cap will be inspected for deterioration, cracks, and other potential problems that could cause exposure to underlying soils. Any area where soils have become or are likely to become exposed will be documented and repairs will be planned.

A log of the inspections and any repairs will be maintained by current and future property owner(s). The log will include recommendations for necessary repair of any areas where the cap is not performing as intended. The inspection log and record of the repairs/maintenance will be kept on site, and will be made available to all interested parties (e.g., WDNR, on-site employees, contractors, future property owners) upon request.

#### 2.3 Maintenance

If damage to the cap is noted during the inspections, or at any other time during the year, repairs will be scheduled as soon as practical. Damage to the cap are significant deficiencies that allow surface water infiltration and direct contact with contaminated soil. Small cracks or

gaps in the cap do not need to be immediately addressed, so long as the overall integrity of the cap is ensured.

Repairs to the cap may include, but are not limited to, patching and filling significant cracks, or resurfacing sections of the site. In the event the paved surfaces or buildings overlying the contaminated soil are removed or replaced, the replacement barrier must be equally impervious and protective. Any replacement barrier will be subject to the same maintenance and inspection guidelines as outlined in this Plan unless indicated otherwise by the WDNR, or its successor.

A record of the repairs/maintenance actions will be kept with the inspection log and copy of the Plan, and will be made available to all interested parties (e.g., WDNR, on-site employees, contractors, future property owners).

In the event that necessary maintenance activities expose the underlying soil, the property owner will inform workers of any direct contact exposure hazard that might exist in a particular work area. The owner will also sample the concrete removed and any soil that is excavated from the site prior to off-site disposal to ascertain if contamination remains. The material will be managed and disposed of by the property owner (or other responsible party) in accordance with applicable local, state, and federal law. Soils may be disposed of as "contaminated" in lieu of sampling if it is likely that characterization would indicate the same. WDNR should be notified of the analytical results within 60 days, or at other interval agreed upon by WDNR.


#### 2.4 Prohibited Activities

The following activities are prohibited unless prior approval, verbal or written, is received from Madison-Kipp Corporation (only until site closure) and WDNR:

- Removal or modification of cap
- Replacement of cap with another barrier, unless it is considered equal
- Excavating or grading of the land surface
- Filling on covered or paved areas
- Plowing or agricultural cultivation
- Construction or placement of a building or other structure
- Changing the use or occupancy of the property, and
- Installation of a water well or soil boring.

Additional testing may be completed to support the WDNR's approval of the aforementioned activities.


4




**BORING LOCATION -**

ABANDONED MONITORING WELL LOCATION PCB MFG BLDG CAP (BRRTS #02-13-578014)

TITLE:





BRRTS #02-13-576860

TOTAL POLYCHLORINATED BI PHENYL ISOCONCENTRATION CONTOUR (MG/KG)

BASE MAP IMAGERY FROM NEARMAP, 4/24/2017. SAMPLE AND CAP LOCATIONS PROVIDED BY


ARCADIS, FEATURES LOCATIONS ARE APPROXIMATE.



**MADISON-KIPP CORPORATION 201 WAUBESA STREET MADISON, WISCONSIN** 

BRRTS #02-18-578014 - PCB BENEATH MFG BLDG **CAP MAINTENANCE PLAN CAP EXTENTS** 

FIGURE 1				
FILE:	269392-003.mxd			
PROJ. NO.:	269392			
DATE:	FEBRUARY 2018			
APPROVED BY:	K. VATER			
CHECKED BY:	B. WACHHOLZ			
DRAWN BY:	B. DEEGAN			



# Appendix A WDNR Form 4400-305

State of Wisconsin Department of Natural Resources dnr.wi.gov

### **Continuing Obligations Inspection and Maintenance Log**

Form 4400-305 (2/14)

Page 1 of 2

Directions: In accordance with s. NR 727.05 (1) (b) 3., Wis. Adm. Code, use of this form for documenting the inspections and maintenance of certain continuing obligations is required. Personal information collected will be used for administrative purposes and may be provided to requesters to the extent required by Wisconsin's Open Records law [ss. 19.31-19.39, Wis. Stats.]. When using this form, identify the condition that is being inspected. See the closure approval letter for this site for requirements regarding the submittal of this form to the Department of Natural Resources. A copy of this inspection log is required to be maintained either on the property, or at a location specified in the closure approval letter. Do NOT delete previous inspection results. This form was developed to provide a continuous history of site inspection results. The Department of Natural Resources project manager is identified in the closure letter. The project manager may also be identified from the database, BRRTS on the Web, at <a href="http://dnr.wi.gov/botw/SetUpBasicSearchForm.do">http://dnr.wi.gov/botw/SetUpBasicSearchForm.do</a>, by searching for the site using the BRRTS ID number, and then looking in the "Who" section.

		and then looking in the "Wh	no" section.		•		
Activity (Site) Name				BRRTS No.			
Inspections are required to be conducted (see closure approval letter):  annually semi-annually other – specify			oproval letter):	When submittal of this form is required, submit the form electronically to the DNR project manager. An electronic version of this filled out form, or a scanned version may be sent to the following email address (see closure approval letter):			
Inspection Date	Inspector Name	Item	Describe the condition of the item that is being inspected	Recommendations for repair or maintena	Previous recommendations implemented?	Photographs taken and attached?	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OY ON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OY ON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OY ON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OYON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OY ON	
		☐ monitoring well ☐ cover/barrier ☐ vapor mitigation system ☐ other:			OY ON	OY ON	

BRRTS No.	Activity (Site) Name	•		Continuing Obligations Inspection and Maintenance Log Form 4400-305 (2/14) Page 2 of 2			
{Click to Add/E	Edit Image}	Date added:	{(	Click to Add/Edit Image}	Date added:		

Title:

Title:

# Appendix B Cap Photo Log



# Photographic Log

Client Name: Madison-Kipp Corporation (MKC) Cap Maintenance Plan – BRRTS #02-13-578014 **Site Location:** Madison, Wisconsin

**Photographer:** Andrew Stehn and Ben Wachholz – TRC Project No.: 269392.0000

Photo No. Date
1 2/6/2018

Description

Previously repaired concrete floor inside MKC facility, facing south




Photo No. Date
2 2/6/2018

Description

Concrete floor inside MKC facility, facing west





## Photographic Log

**Client Name:** 

Madison-Kipp Corporation (MKC) Cap Maintenance Plan – BRRTS #02-13-578014 **Site Location:** Madison, Wisconsin

**Photographer:** Andrew Stehn and Ben Wachholz – TRC Project No.: 269392.0000

Photo No.

**Date** 2/6/2018

Description


Concrete floor inside MKC facility near loading dock, facing northeast



Photo No. Date
4 2/6/2018

Description

Previously repaired concrete floor inside MKC facility showing areas covered in polyurethane, facing southeast





# Photographic Log

**Client Name:** 

Madison-Kipp Corporation (MKC) Cap Maintenance Plan – BRRTS #02-13-578014

Date

**Site Location:** Madison, Wisconsin

**Photographer:** Andrew Stehn and Ben Wachholz – TRC Project No.: 269392.0000

**Photo No.** 5

2/6/2018

Description

Concrete floor inside MKC facility, facing west





Photo No.

6 2/6/2018

Date

Description

Concrete floor inside MKC facility, facing south



# Appendix C Cover Maintenance Plan for BRRTS #02-13-576860 (Arcadis, 2016)

#### **COVER OF BARRIER MAINTENANCE PLAN**

(to be included in Form 4400-202, as Attachment D)

February 10, 2016

Property Located at:

201 Waubesa St., Madison, WI 53704

DNR BRRTS/Activity #, FID # 113125320

Parcel ID: 071005308012

Introduction

This document is the Maintenance Plan for a cap at the above-referenced property in accordance with the requirements of s. NR 724.13 (2), Wis. Adm. Code. The maintenance activities relate to the existing cap which addresses or occupies the area over the contaminated groundwater plume or soil.

More site-specific information about this property/site may be found in:

- The case file in the DNR Madison office
- <u>BRRTS on the Web</u> (DNR's internet based data base of contaminated sites) for the link to a PDF for site-specific information at the time of closure and on continuing obligations;
- RR Sites Map/GIS Registry layer for a map view of the site, and
- The DNR project manager for Dane County.

#### **D.1.** Descriptions:

(Form 4400-202, Attachment D, Part D1. – brief description of the type, depth and location of residual contamination, description of the system/cover/barrier to be maintained, and its location on the site, maintenance activities, and contact information.)

#### **Description of Contamination**

VOCs- soil VOC concentrations were reported above the industrial direct contact RCL generally near the former oil shed in the upper 2 feet of soil. Soil VOC concentrations were reported above the soil to groundwater pathway RCL in the north parking lot.

PCBs - soil PCB concentrations were reported above the industrial direct contact RCL at depths from 0 to 4 feet bls and greater than 4 feet bls. PCB concentrations were generally observed along the western property line and in the north parking lot in the upper 4 feet of soil. Residual PCB concentrations are less than 50 mg/kg on Site and will remain under a cap. Residual PCB concentrations at the site boundary are less than 1 mg/kg.

PAH- Soil PAH concentrations were reported above the industrial direct contact RCL from 0 to 4 feet and at two soil borings advanced to depths greater than 4 feet.

RCRA Metals - Arsenic was detected in all soil samples analyzed with concentrations ranging from 0.37 to 100 mg/kg. The average and geometric mean for the arsenic concentrations were 6.3 mg/kg and 4.5 mg/kg, respectively. Based on the widespread distribution of arsenic in the soil within such a narrow range of concentrations, the presence of arsenic appears to represent naturally occurring background conditions.

Soil RCRA metal concentrations, excluding arsenic, were reported above the industrial direct contact RCL in Soil Boring B-54 in the north parking lot for lead (5,600 mg/kg) and mercury (19 mg/kg). These metals were delineated vertically by soil samples analyzed from the same borings or an adjacent boring and horizontally by adjacent borings and/or off-Site soil samples collected from the adjacent residential properties. Soil metal concentrations were reported above the soil to groundwater pathway RCL in 10 soil borings for barium, mercury, lead, or selenium from depths greater than 4 feet bls.

#### <u>Description of the Barrier to be Maintained</u>

The cap consists of 6" asphalt in the north parking lot, 3" asphalt in the southeast parking lot and 3" concrete in along the east side of the facility building as shown on Figure D.2.

#### **Barrier Purpose**

The asphalt and concrete cap over the contaminated soil serves as a barrier to prevent direct human contact with residual soil contamination that might otherwise pose a threat to human health. The cover/barrier also acts as a partial infiltration barrier to minimize future soil-to-groundwater contamination migration that would violate the groundwater standards in ch. NR 140, Wisconsin Administrative Code. Based on the current use of the property, industrial, the barrier should function as intended unless disturbed.

#### **Annual Inspection**

The asphalt and concrete cap overlying the contaminated soil and as depicted in Figure D.2 will be inspected once a year, normally in the spring after all snow and ice is gone, for deterioration, cracks and other potential problems that can cause exposure to underlying soils. The inspections will be performed by the property owner or their designated representative. The inspections will be performed to evaluate damage due to settling, exposure to the weather, wear from traffic, increasing age and other factors. Any area where soils have become or are likely to become exposed will be documented.

A log of the inspections and any repairs will be maintained by the property owner and is included as D.4, Form 4400-305, Continuing Obligations Inspection and Maintenance Log. The log will include recommendations for necessary repair of any areas where underlying soils are exposed and where infiltration from the surface will not be effectively minimized. Once repairs are completed, they will be documented in the inspection log. A copy of the maintenance plan and inspection log will be kept at the site; or, if there is no acceptable place (for example, no building is present) to keep it at the site, at the address of the property owner and available for submittal or inspection by Wisconsin Department of Natural Resources (DNR) representatives upon their request.

[Note: The DNR may, in some instances, require in the case closure letter that the inspection log be submitted at least annually after every inspection. If the case closure letter requires that, then add the following sentence to the paragraph above: A copy of the inspection log must be submitted electronically to the DNR after every inspection, at least annually.]

#### **Maintenance Activities**

(Form 4400-202, Attachment D, Part D1. – Description of Maintenance Actions required for maximizing effectiveness of the cover/barrier/engineered control, feature or other action for which maintenance is required.)

If problems are noted during the annual inspections or at any other time during the year, repairs will be scheduled as soon as practical. Repairs can include patching and filling or larger resurfacing or construction

operations. In the event that necessary maintenance activities expose the underlying soil, the owner must inform maintenance workers of the direct contact exposure hazard and provide them with appropriate personal protection equipment (PPE). The owner must also sample any soil that is excavated from the site prior to disposal to ascertain if contamination remains. The soil must be treated, stored and disposed of by the owner in accordance with applicable local, state and federal law.

In the event the asphalt and concrete cap overlying the contaminated soil are removed or replaced, the replacement barrier must be equally impervious. Any replacement barrier will be subject to the same maintenance and inspection guidelines as outlined in this Maintenance Plan unless indicated otherwise by the DNR or its successor.

The property owner, in order to maintain the integrity of the asphalt and concrete cap, will maintain a copy of this Maintenance Plan at the site; or, if there is no acceptable place to keep it at the site (for example, no building is present), at the address of the property owner and make it available to all interested parties (i.e. on-site employees, contractors, future property owners, etc.) for viewing.

#### Prohibition of Activities and Notification of DNR Prior to Actions Affecting a Cover/Barrier

The following activities are prohibited on any portion of the property the engineered cap is required as shown on the attached map, unless prior written approval has been obtained from the Wisconsin Department of Natural Resources: 1) removal of the existing barrier; 2) replacement with another barrier; 3) excavating or grading of the land surface; 4) filling on capped or paved areas; 5) plowing for agricultural cultivation; 6) construction or placement of a building or other structure; 7) changing the use or occupancy of the property to a residential exposure setting, which may include certain uses, such as single or multiple family residences, a school, day care, senior center, hospital, or similar residential exposure settings;

If removal, replacement or other changes to a cover, or a building which is acting as a cover, are considered, the property owner will contact DNR at least 45 days before taking such an action, to determine whether further action may be necessary to protect human health, safety, or welfare or the environment, in accordance with s. NR 727.07, Wis. Adm. Code.

#### Amendment or Withdrawal of Maintenance Plan

This Maintenance Plan can be amended or withdrawn by the property owner and its successors with the written approval of DNR.

#### **Contact Information**

(Form 4400-202, Attachment D, Part 1.) Contact Information, including the name, address and phone number of the individual or facility who will be conducting the maintenance.)

February 2016	
Site Owner and Operator:	Madison-Kipp Corporation 201 Waubesa St., Madison, WI 53704 608-242-5200
Signature:	
(DNR may request signature	of affected property owners, on a case-by-case basis)

Property Owner: Madison-Kipp Corporation

201 Waubesa St., Madison, WI 53704

608-242-5200

Signature:

Consultant: Arcadis, U.S.

126 N Jefferson St. Suite 400, Milwaukee, WI 53202

414-276-7742

DNR: Michael Schmoller

Wisconsin Department of Natural Resources

South Central Region 3911 Fish Hatchery Road Fitchburg, WI 53711

#### D.2 Location Map(s)

*Include a location map which shows:* 

- (1) the feature that requires maintenance;
- (2) the location of the feature(s) that require(s) maintenance: on and off the source property;
- (3) the extent of the structure or feature(s) to be maintained, in relation to other structures or features on the site;
- (4) the extent and type of residual contamination; and
- (5) all property boundaries.

#### D. 3 Photographs of Cover/Barrier

Include one or more photographs documenting the condition and extent of the cover/barrier/building/slab at the time of the closure request. Pertinent features must be visible and discernible. Include a title on each photograph, which identifies the site name and location of the feature, and the date on which the photograph was taken.

#### D.4 Continuing Obligations Inspection and Maintenance Log

Use DNR Fillable Form Form 4400-305

#### **Monitoring Well Maintenance Plan Template**

D.1. Descriptions and Contact Information: (Form 4400-202, Attachment D, Part 1.)

#### **Descriptions:**

- Provide a description of which wells were kept/required for continued monitoring.
- Provide a description of the well lock, well seal type/materials and condition at the time of closure. Reference the sampling plan.
- Describe the maintenance activities which will be conducted.
- Inspections are to be conducted on a yearly basis. Inspections are recommended in spring after snow and ice are gone. In accordance with s. NR 716.13 (14), Wis. Adm. Code, verify the integrity of the well labels, lock and seal. Determine whether the wells are providing a conduit to the subsurface.
- Describe the actions to be taken if the well label is missing, the well lock is broken, or the well seal is no longer sealing the annular space from surface contamination.
- Describe in which situations the well should be abandoned in accordance with s. NR 141, Wis. Adm.
   Code.
- Identify where the maintenance plan and inspection report will be located.

Contact	Intorm	ation
Contact	11110111	auvii.

[MONTH & YEAR]
Person Conducting the Inspection and maintenance:
[NAME]

[ADDRESS] [PHONE #]

Signature:

Consultant: [NAME]

[ADDRESS] [PHONE #]

DNR: [PROJECT MANAGER NAME]

[ADDRESS] [PHONE #]

#### D.2. Location Map:

 Provide a location map showing the well location in relation to the property boundaries, buildings, etc. (The site location map from the Site Investigation Report should suffice.) Wells locations are required to be surveyed in accordance with s. NR 141.065 (2), Wis. Adm. Code.

#### D.3. Photograph of Monitoring Well:


- Include one or more photographs documenting the condition and extent of the well lock and seal the time of the closure request. Pertinent features must be visible and discernible.
- Include a title on each photograph, which identifies the site name and location of the feature, and the date on which the photograph was taken.
- D.4. Continuing Obligations Inspection and Maintenance Log Use DNR Fillable Form 4400-305






Madison-Kipp Corporation Madison, Wisconsin

6-inch cap in north parking lot (facing west) *Photo: June 8, 2015* 



6-inch cap in north parking lot (facing north) *Photo: June 8, 2015* 

Madison-Kipp Corporation Madison, Wisconsin




6-inch cap in north parking lot (facing north) *Photo: June 8, 2015* 



3-inch concrete cover along east property boundary(facing north) *Photo: January 30, 2016* 

Madison-Kipp Corporation Madison, Wisconsin



3-inch cap in southeast parking lot (facing southeast) Photo: January 30, 2016



3-inch cap in southeast parking lot (facing west) *Photo: January 30, 2016* 

State of Wisconsin Department of Natural Resources dnr.wi.gov

### **Continuing Obligations Inspection and Maintenance Log**

Form 4400-305 (2/14)

Page 1 of 2

Directions: In accordance with s. NR 727.05 (1) (b) 3., Wis. Adm. Code, use of this form for documenting the inspections and maintenance of certain continuing obligations is required. Personal information collected will be used for administrative purposes and may be provided to requesters to the extent required by Wisconsin's Open Records law [ss. 19.31-19.39, Wis. Stats.]. When using this form, identify the condition that is being inspected. See the closure approval letter for this site for requirements regarding the submittal of this form to the Department of Natural Resources. A copy of this inspection log is required to be maintained either on the property, or at a location specified in the closure approval letter. Do NOT delete previous inspection results. This form was developed to provide a continuous history of site inspection results. The Department of Natural Resources project manager is identified in the closure letter. The project manager may also be identified from the database, BRRTS on the Web, at <a href="http://dnr.wi.gov/botw/SetUpBasicSearchForm.do">http://dnr.wi.gov/botw/SetUpBasicSearchForm.do</a>, by searching for the site using the BRRTS ID number, and then looking in the "Who" section.

Activity (Site) Name							
Activity (Site) Name				BRRTS No.			
Inspections are required to be conducted (see closure approval letter):  annually semi-annually other – specify			•	When submittal of this form is required, submit the form electronically to the DNR project manager. An electronic version of this filled out form, or a scanned version may be sent to the following email address (see closure approval letter):			
Inspection Date	Inspector Name	Item	Describe the condition of the item that is being inspected	Recommendations for repair or maintena	Previous recommendations implemented?	Photographs taken and attached?	
	,	monitoring well cover/barrier vapor mitigation system other:			OY ON	O Y O N	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	O Y O N	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OYON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OYON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OYON	
		monitoring well cover/barrier vapor mitigation system other:			OY ON	OYON	

RRTS No. Activity (Site) Name

Continuing Obligations Inspection and Maintenance Log
Form 4400-305 (2/14)

Page 2 of 2

{Click to Add/Edit Image}

Date added:

{Click to Add/Edit Image}

Date added:

Title:

Title: